



Greens Creek Annual Meeting June 8, 2010

Agenda

Overview

Hecla

- Tailings Annual Report Summary
- Tailings FWMP Report Summary
- Site 23 Annual Report Summary
- 920 FWMP Annual Report Summary
- Biomonitoring Report Summary
- Wednesday Tour Details
- NPDES Permit Overview

Overview

- Problems and important events
- Production statistics
- Exploration activities
- Inspections

Hecla

- Spills and releases
- Disturbances and water usage
- Construction activities
- 2010 planned projects
- Reclamation activities



2009 Production Statistics

- 2150 tons/day mined
- 2167 tons/day milled
- 16 shipments of cons
 - 173,000 tons

Hecla



Exploration Statistics

• 2009 Activities

Hecla

- Drilled 5 holes (8,778 feet)
- All pads were in immediate mine area
- Continued same environmental controls as developed in the 2004-2005 drill seasons
- 2010 Plans
 - 13 holes at 8 sites (20,000 feet)
 - Currently restricted by Roadless Rule



Inspections

- USFS: 12
- ADEC: 5
- EPA: 1
- CBJ: 1

Heca GREENS CREEK

2009 Spills

Date	Location	Quantity spilled (gal)	Spilled material	Description of Incident
3/11/09	con shed	400		Pipeline in the con shed broke, likely due to previous freezing and subsequent thawing.
6/1/09	6.7 B road	183,000-425,000		hole in 8" stormwater line was found; leak was likely caused in Oct. 08
6/9/09	4.1 B road	82,000 - 166,000		hole in 10" line was found in a seam; likely caused in Oct. 08
7/23/09	4.6 B road	300-400		new pipeline connection into the 8" stormwater line at Site E failed when put under pressure
8/11/09	portal/Greens Creek	5000	drill mud/water	while drilling, permeable material was encountered that allowed the drill mud to flow away from the drill site and downgradient to seeps that entered Greens Creek
9/23/09	HI truck pad	15 lbs		copper sulfate leaked from a hole in the bottom of a seavan onto the top of another seavan

Disturbances and Water Usage

• No new disturbances

Hecla

- Up to 700 gpm Greens Creek withdrawal (creek flow dependent) for mine and mill use
- Variable Cannery Creek withdrawal for truck wash, camp and port uses

2009 Construction Activities

• Commissioned Pond 6

Hecla

- Built lined degrit basins at Tailings
- Dug test pits in the East Ridge
- Replaced intake screens in Greens Creek
- Replaced concentrate storage building roof

2010 Planned Activities

• East Ridge

Hecla

- Geotechnical drilling program
- Sand pit
- Resurfacing 920 area
- Field surveys
- Install fish pass

Reclamation Activities

- 2009 completed production rock removal
 - Site E: 40,000 cubic yards
 - Pond D berm: 4500 cubic yards
- 2010 planned production rock removal
 - Site E

Hecla

- Site 1350
- Closure projects ongoing



Pond D Activities August 2009, showing replacement of berm material