




## KENSINGTON MINE INSPECTION REPORT

**Inspection Date:** August 21, 2019  
**Weather:** partly cloudy, ~50-60 ° F  
**Time of Inspection:** 10:00am to 6:00pm  
**Operator Contact:** Pete Strow - CAK Environmental Manager  
**Agency Personnel:** ADNR-Shannon Kelly; USFS-Richard Dudek; ADEC-David Khan  
**Inspection Objectives:** General Mine Site Inspection

Agency personnel drove to Ward Air to take the 10am flight on a float plane to the Slate Cove Marine Terminal. We returned via the Kensington evening boat to Yankee Cove followed by bus back to the airport. The following observations were made, and photographs taken:



Comet Waste Rock Stockpile, Comet Water Treatment Plant, and Lynn Canal in the background



Comet Portal and road to Water Treatment Plant

Comet Water Treatment Plant Pond 1



Comet Water Treatment Plant Pond 2



Temporary surface storage of material dredged from Water Treatment Plant ponds, prior to underground placement.



White material present on test rock in Water Treatment Plant



Bottom of the Spillway at the (TTF), discharges into East Fork Slate Creek



Tailing Treatment Facility (TTF) upstream face of dam



Tailing Treatment Facility (TTF)



Tailing Treatment Facility (TTF), Lions head in background



Graphitic phyllite barrel leachate testing





Temporary surface stockpile of Graphitic Phyllite material at Pit 4, actively being placed underground



Mill bench area where old Gen Sets have been removed

Test Plots on slope in  
Snow-slide Gulch



Thanks to Pete Strow for the tour.

Sincerely,

Shannon M. Kelly  
Mining Engineer

cc: Steve Buckley, DNR  
Richard Dudek, USFS  
Kevin Eppers, CAK  
David Khan, DEC  
Brent Martellaro, DNR  
Kyle Moselle, DNR