



KENSINGTON SITE VISIT REPORT

Inspection Date: July 13, 2021

Weather: Overcast, ~60 ° F

Time of Site Visit: 5:00am to 5:00pm

Operator Contact: Kevin Eppers (Coeur Alaska) & Dave Casey (HDR)

Agency Personnel: ADNR (Shannon Kelly, Sylvia Kreel, Cathe Heroy, Charlie Cobb); ADF&G (Kate Kanouse); ADEC (David Khan); USFS (Matt Reece, Casey Loofburrow, Pat Dryer)

Inspection Objectives: General Mine Site Visit, State Permitting kick-off

Agency personnel arrived at Engineer's Cut-Off Road Coeur Alaska parking lot at 4:30am to catch the bus to the crew boat to meet Mr. Kevin Eppers for an agency tour of the Kensington mine. The following observations were made, and photographs taken:



Tailings facility and tailings dam.



Tailings Facility



Agency Group on top of tailings dam, supersak sandbags being used instead of berms.



Photo taken from on top of knob above tailings dam.



Photo taken from on top of knob above tailings facility, looking towards Lionshead peak.



Kensington waste rock stockpile.



Comet water treatment plant, pond 1 and 2 are very full, filter bags on the right side are also full.



Pond 1 at the Comet water treatment plant.



Looking up at the Comet waste rock stockpile, from the Comet water treatment plant.




Discharge at Sherman creek, beyond Comet water treatment plant.



Hoses coming downhill from discharge line.



Sherman Creek



Comet waste rock stockpile in background.

Sincerely,

Shannon M. Kelly
Mining Engineer

cc: Steve Buckley, DNR
Matt Reece, USFS
David Khan, DEC
Sylvia Kreel, DNR OPMP
Kevin Eppers, Coeur Alaska
Brent Martellaro, DNR