





NIBLACK INSPECTION REPORT

Inspection Date: April 22, 2019
Weather: Cloudy, ~40 ° F
Time of Inspection: 12:00pm to 3:00pm
Operator Contact: Graham Neale, Project Manager
Agency Personnel: Shannon Kelly, Mining Engineer, ADNRR
Inspection Objectives: General Site Visit

The following observations were made, and photographs taken:



Floating barge camp facilities



Rooms inside floating camp



Road from dock/camp facility up to other areas of the exploration project



Fuel storage



Road up to underground exploration adit



Underground exploration adit



Settling ponds



Settling ponds with water treatment facility at back



Inside water treatment facility



Land Application/Dispersment (LAD) system



Fully lined PAG rock storage pile



Fully lined and covered low-grade PAG ore pile



Dock/floating camp facility from road



Looking back into the Niblack Anchorage bay

Thanks to Graham for a safe trip to the Niblack exploration project.

Sincerely,

Shannon M. Kelly
Mining Engineer

cc: Steve Buckley, DNR
Brent Martellaro, DNR