

10548

WATER WELL RECORD
STATE OF ALASKA
DEPARTMENT OF NATURAL RESOURCES
Division of Geological & Geophysical Surveys

LOCATION OF WELL (Please complete either 1a, 1b or 1c.)

Drilling Permit No. _____
A.D.L. No. _____

1a. Borough ANCH	Subdivision KNIK	Lot 6	Block 1	1b. 1/4 qtrs. — of — of — of —	Section No.	Township N ☐ S ☐	Range E ☐ W ☐	Meridian
----------------------------	----------------------------	-----------------	-------------------	-----------------------------------	-------------	---	--	----------

1c. DISTANCE AND DIRECTION FROM ROAD INTERSECTIONS Street Address and Area of Well Location	3. OWNER OF WELL: Address: DARYL GALYAN 4601 SHELLBORN ANCH AK 99516
--	--

2. WELL LOG Material Type	Feet Below Surface		4. WELL DEPTH: (final) 387 ft.	5. DATE OF COMPLETION 30 - SEPT-85
	Top	Bottom		
ORGANIC SOIL BROWN	0	4	6. ☐ Cable tool ☒ Rotary ☐ Driven ☐ Dug ☐ Auger ☐ Jetted ☐ Bored ☐ Other:	7. USE: ☒ Domestic ☐ Public Supply ☐ Industry ☐ Irrigation ☐ Recharge ☐ Commerical ☐ Test Well ☐ Other:
SILTY SANDY GRAVEL BRN DAMP	4	25		
" GRAVELLY SAND "	25	53	8. CASING: ☐ Threaded ☒ Welded diam. 6 in. to 185 ft. Depth Weight 17.2 lbs./ft. diam. _____ in. to _____ ft. Depth Stickup 2 ft.	9. FINISH OF WELL: Type: _____ Diameter: _____ Slot/Mesh Size: _____ Length: _____ Set between _____ ft. and _____ ft. Backfilling _____ Gravel pack _____
" SANDY GRAVEL "	53	115		
AS ABOVE, VERY DENSE, BOULDERS.	115	124	10. STATIC WATER LEVEL: 198 ft. 9/30/85 ☐ Above or ☒ Below land surface Date Equipment used: SANDER	11. PUMPING LEVEL below land surface and YIELD 385 ft. after 1 hrs. pumping 1/2 g.p.m. _____ ft. after _____ hrs. pumping _____ g.p.m.
SILTY SANDY GRAVEL MUST RUST BROWN	124	128		
CLAYEY SDY GR WET * GREY BROWN	128	134	12. GROUTING Well Grouted: ☐ Yes ☐ No Material: ☐ Neat Cement ☐ Other: _____	13. PUMP: (if available) HP _____ Length of Drop Pipe _____ ft. capacity _____ g.p.m. ☐ Subm. ☐ Jet ☐ Centrifical ☐ Other
GRAVELLY SILTY SAND GRY BRN	134	183		
* OVERNITE @ 180' NO WATER IN HOLE AM NEXT DAY.			14. REMARKS: SHUT DOWN & WAITED FOR WATER TO ENTER ZONE 128-134. UNABLE TO PUMP ANY WATER BY AIR LIFT. PERFORATIONS 128-134 COULD PRODUCE	15. Water Temperature SMALL AMT. H2O
BROWN BEDROCK. MOD HARD SHALE-SLATE	183	230		
GRADATIONAL COLOR CHANGE, GREY	230	385		
WATER FROM FRACTURES & CRACKS IN BEDROCK				
W. N. WHITE WELL DRILLING				
12221 Hilltop Drive				
Anchorage, Alaska 99515				
NOTE:				
MOVED RIG BACK 5 OCT 85 AND PERFORATED INTERVAL 128-134				
4 ROWS 45 PERFS / ROW. COULD HEAR WATER RUNNING IN.				
WATER LEVEL TO 178' IN ONE HOUR				

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief;

W. N. WHITE DRILLING
Registered Business Name

A-10760
Contract License Number

Address: **12221 HILLTOP**

Signed: **Walter N. White**
Authorized Representative

Date: **30 SEPT 85**