

SB 12-3-13DD

DAILY DRILLING LOG SYREN BROS. DRILLING, INC.

Anchorage, Alaska 99503

274-6437

Stan Marquiss

DEPTH OF WELL 245 feet

19408 Marmot Circle Anch., Ak. 502

STATIC LEVEL OF WATER FT. 60' from ground level

Lot 14 Blk 7 Kasilof Hills Sub.

DRAW DOWN FT.

5-25-79

GALS. PER HR. one (1) gallon per minute

5-26-79

KIND OF CASING 171b. grade 6" steel casing

KIND OF FORMATION:

FROM 0	FT. TO 11	FT. clay, gravel	FROM	FT. TO	FT.
FROM 11	FT. TO 20	FT. sand, gravel, with clay base	FROM	FT. TO	FT.
FROM 20	FT. TO 28	FT. sand, gravel	FROM	FT. TO	FT.
FROM 28	FT. TO 38	FT. brown sand, gravel	FROM	FT. TO	FT.
FROM 38	FT. TO 245	FT. bed rock	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.
FROM	FT. TO	FT.	FROM	FT. TO	FT.

MISC. INFORMATION: All water was picked up in bedrock, most of it from 50-70 feet and some at the 180-240 foot area. A well guard is recommended for the top of pump.

DRILLER'S NAME Kermit D. Syren

15263

15263(1)

15263(2)

M-W DRILLING, Inc.

P.O. Box 110378 • 10330 Old Seward Highway
(907) 349-8535
ANCHORAGE, ALASKA 99511

DRILLING LOGWell Owner CLAIRE DOIGUse of Well DOMESTIC

Location (address of: Township, Range, Section, if known; or distance main road

10221 STROGANOFF DRIVEANCHORAGE, ALASKASize of casing 6" Depth of Hole 405 feet Cased to U/K feetStatic water level 226 ft. (above) (below) land surface. Finish of well (check one) open end (X);Screen (); Perforated ().Describe screen or perforation N/AWell pumping test at 2.5 gallons per (hour) (minute) for 48 hours with 176 ft. of drawdown from static level.Date of completion 12 SEPTEMBER 1995

NOTE: WELL DEEPENING

WELL LOGDepth in feet from
ground surface

Give details of formations penetrated, size of material, color and hardness

0 TO 250EXISTING WELL250 TO 355BEDROCK: SILTSTONE ARGILITE, GREY355 TO 380N/A: SOME FRACTURES / QUARTZ SEAMS WITH SMALL WATER SEAPS380 TO 405SILTSTONE ARGILITETOTOTOTOTOTOTOTOTOTOTO

Do not Send Deepenings to State