

LOCATION: 6.W. 4, N.E. 4, S.E. 4, SEC. 17, T.13N., R.3W., SEWARD MERIDIAN					GROUND SURFACE ELEVATION: 102±		
DEPTH (FEET)	BLOWS (N IN)	GRAIN SIZE			SAMPLE INTERVAL	GRAPHIC LOG	LITHOLOGIC LOG
		% GRAVEL	% SAND	% FINES			
0	80	35	5			GP	Gravel w/sand; few fines, dry.
5	10	85	5			SW	Sand w/gravel; grey, no fines, well-graded sand w/sub-angular sand <0.125" diameter, round gravel < 1.0" diameter. Examined cuttings.
10	1	05	4			SP	Sand; grey, clean, sub-rounded with trace gravel <1.0" diameter rocks subrounded, poorly graded. Split-spoon sample.
15							
20							Same as 10.0 ft. Split-spoon sample.
25							
30							Same as 20.0 ft. Split-spoon sample. Water table at 25.0 to 32.0 ft. Precise depth to water unknown.
35	0	0	100			ML	Silt with abundant clay; grey, medium plasticity, saturated. Sampled with split-spoon.

PROJECT NO. 1957.0101

James M. Montgomery
Consulting Engineers Inc.

ABANDONED

LOCATION: **Merrill Field Landfill**
(11th and Orca)

PAGE 1 OF 2

Solid Waste Services
Soil Boring Log
MFL-CL-36B

SB 13-3-17 CDAC

22042

LOCATION: S.W. 4, N.E. 4, S.E. 4, S.W. 4, SEC. 17, T.13N., R.3W., SEWARD MERIDIAN					GROUND SURFACE ELEVATION: 102±			
DEPTH (FEET)	BLOWS (4 IN)	GRAIN SIZE			SAMPLE INTERVAL	GRAPHIC LOG	Engineer/Geologist: <u>Wayne McFadden</u> Drilling Contractor: <u>Discovery Drilling</u> Boring Type: <u>HSA Split-Spoon</u> Boring Diameter: <u>4-Inches</u>	Date: <u>3/16/92</u> Drill Rig: <u>Tire</u>
		% GRAVEL	% SAND	% FINES				
35	0	0	100		ML	LITHOLOGIC LOG		
35						Silt with abundant clay; grey. Examined cuttings.		
40								
45								
50						Bottom of hole abandoned with bentonite grout.		
50						BOTTOM OF BORING AT 51.0'		
55								
60								
65								

JMM James M. Montgomery
Consulting Engineers Inc.



LOCATION: Merril Field Landfill
(11th and Orca)

PAGE 2 OF 2

Solid Waste Services
Soil Boring Log
MFL-CL-36B

PROJECT NO. 1957.0101

SB 13-3-17CDAC